

**NVL Laboratories, Inc.**

4708 Aurora Ave N, Seattle, WA 98103  
Tel: 206.547.0100 Emerg. Pager: 206.344.1878  
1.888.NVL.LABS (885.5227)

**CHAIN of CUSTODY  
SAMPLE LOG**

BATCH ID

**2309982.00**Client **PDG-Project Development Group, Inc.**

NVL Batch Number

Street **11814 NE 116th St.**

Client Job Number

**No Job ID Numbers**

Total Samples

**4**City **Kirkland, WA 98034**

Turn Around Time

☐ 1-Hr ☒ 2-Hrs ☐ 4 Days☐ 2-Hrs ☐ 2 Days ☐ 5 Days☒ 4-Hrs ☐ 3 Days ☐ 6 to 10 Days

Please call for TAT less than 24 Hrs

Project Manager **Robin Burnham**Project Location **Tully's**

Email address

Phone: (425) 825-1812

Fax: (425) 821-2895

Cell: (206) 715-0330

Alt Fax (425) 821-2895

<input type="checkbox"/> Asbestos Air	<input type="checkbox"/> PCM (NIOSH 7400)	<input type="checkbox"/> TEM (NIOSH 7402)	<input type="checkbox"/> TEM (AHERA)	<input type="checkbox"/> TEM (EPA Level II)	<input type="checkbox"/> Other
<input checked="" type="checkbox"/> Asbestos Bulk	<input type="checkbox"/> PLM (EPA/600/R-93/118)	<input type="checkbox"/> PLM (EPA Point Count)	<input type="checkbox"/> PLM (EPA Gravimetry)	<input type="checkbox"/> TEM Bulk	
<b>METALS</b>	<b>Det. Limit</b>	<b>Matrix</b>	<b>RCRA Metals</b>	<b>All 8</b>	<b>Other Metals</b>
<input type="checkbox"/> Total Metals	<input type="checkbox"/> ppm (AAS)	<input type="checkbox"/> Air Filter	<input type="checkbox"/> Arsenic (As)	<input type="checkbox"/> Lead (Pb)	<input type="checkbox"/> All 3
<input type="checkbox"/> TCLP	<input type="checkbox"/> ppb (GFAA)	<input type="checkbox"/> Drinking water	<input type="checkbox"/> Barium (Ba)	<input type="checkbox"/> Mercury (Hg)	<input type="checkbox"/> Copper (Cu)
		<input type="checkbox"/> Dust/wipe	<input type="checkbox"/> Cadmium (Cd)	<input type="checkbox"/> Selenium (Se)	<input type="checkbox"/> Nickel (Ni)
		<input type="checkbox"/> Soil	<input type="checkbox"/> Chromium (Cr)	<input type="checkbox"/> Silver (Ag)	<input type="checkbox"/> Zinc (Zn)
<input type="checkbox"/> Other Types of Analysis	<input type="checkbox"/> Fiberglass	<input type="checkbox"/> Nuisance Dust	<input type="checkbox"/> Rotometer Calibration	<input type="checkbox"/> Other (Specify)	
	<input type="checkbox"/> Silica	<input type="checkbox"/> Respirable Dust	<input type="checkbox"/> Mold/Fungus (Please use Mold COC)		

**Condition of Package:**

Seq. #	Lab ID	Client Sample Number	Comments	A/R
1		T-01		A
2		T-02		A
3		T-03		A
4		T-04		A
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				

	Print Below	Sign Below	Company	Date	Time
Sampled by	Melanie Bica	Melanie Bica	PDG, INC	7-25-03	
Relinquished by	Melanie Bica	Melanie Bica	PDG, INC	7-25-03	
Received by	J. Browne	J. Browne	NVL	7-28-03	0800
Analyzed by	J. EVANS	J. Evans	NVL	7/28/03	12:40
Results Called by					
Results Faxed by					12:45

Special Instructions: Unless requested in writing, all samples will be disposed of two (2) weeks after analysis.

Please Fax Results to Hector

**NVL Laboratories, Inc.**4708 Aurora Ave. N., Seattle, WA 98103  
Tel: 206.547.0100, Fax: 206.634.1936  
www.nvllabs.com

NVLAP

#102063

**Bulk Asbestos Fibers Analysis**

By Polarized Light Microscopy

Client: PDG-Project Development Group, Inc.

Address: 11814 NE 116th St.

Kirkland, WA 98034

Attention: Mr. Robin Burnham

Project Location: Tully's

Batch #: 2309982.00

Client Project #: n/a

Samples Received: 4

Samples Analyzed: 4

Method: EPA/600R-93/116

**Lab ID : 23063698 Client Sample #: T-01**

Location: Tully's

Layer 1 of 3 Description: Multiple layers of white paint

Non-Fibrous Materials:

Fine particles, Paint

Other Fibrous Materials: %

None Detected ND

Asbestos Type: %

None Detected ND

Layer 2 of 3 Description: White fiber-reinforced compound

Non-Fibrous Materials:

Fine particles, Binder/Filler

Other Fibrous Materials: %

Glass fibers 25%

Asbestos Type: %

Chrysotile 3%

Layer 3 of 3 Description: Brittle black foam

Non-Fibrous Materials:

Glass particles

Other Fibrous Materials: %

None Detected ND

Asbestos Type: %

None Detected ND

**Lab ID : 23063699 Client Sample #: T-02**

Location: Tully's

Layer 1 of 3 Description: Multiple layers of white paint

Non-Fibrous Materials:

Fine particles, Paint

Other Fibrous Materials: %

None Detected ND

Asbestos Type: %

None Detected ND

Layer 2 of 3 Description: White fiber-reinforced compound

Non-Fibrous Materials:

Fine particles, Binder/Filler

Other Fibrous Materials: %

Glass fibers 25%

Asbestos Type: %

Chrysotile 3%

Layer 3 of 3 Description: Brittle black foam

Non-Fibrous Materials:

Glass particles

Other Fibrous Materials: %

None Detected ND

Asbestos Type: %

None Detected ND

**Lab ID : 23063700 Client Sample #: T-03**

Location: Tully's

Layer 1 of 2 Description: Multiple layers of white and off-white paint

Non-Fibrous Materials:

Fine particles, Paint

Other Fibrous Materials: %

None Detected ND

Asbestos Type: %

None Detected ND

Layer 2 of 2 Description: Foil-backed felt and cloth wrap

Non-Fibrous Materials:

Adhesive/binder, Metal foil

Other Fibrous Materials: %

Cellulose 85%

Asbestos Type: %

None Detected ND

**Lab ID : 23063701 Client Sample #: T-04**

Location: Tully's

Sampled by: Client

Analyzed by: Carol Evans

Date: 07/28/2003

**DRAFT**

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using EPA 600/R-93/116 Method with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government.

**NVL Laboratories, Inc.**

NVLAP

4708 Aurora Ave. N., Seattle, WA 98103  
Tel: 206.547.0100, Fax: 206.634.1936  
www.nvllabs.com

#102063

**Bulk Asbestos Fibers Analysis**

By Polarized Light Microscopy

Client: PDG-Project Development Group, Inc.

Batch #: 2309982.00

Address: 11814 NE 116th St.

Client Project #: n/a

Kirkland, WA 98034

Samples Received: 4

Attention: Mr. Robin Burnham

Samples Analyzed: 4

Project Location: Tully's

Method: EPA/600R-93/116

Layer 1 of 3	Description: Multiple layers of white paint	Non-Fibrous Materials: Fine particles, Paint	Other Fibrous Materials: % None Detected ND	Asbestos Type: % None Detected ND
Layer 2 of 3	Description: White woven fabric encased in white compound	Non-Fibrous Materials: Fine particles, Binder/Filler	Other Fibrous Materials: % Cellulose 25%	Asbestos Type: % Chrysotile 3%
Layer 3 of 3	Description: Brittle black material	Non-Fibrous Materials: Glass foam, Fine particles	Other Fibrous Materials: % None Detected ND	Asbestos Type: % None Detected ND

Sampled by: Client

Analyzed by: Carol Evans

Date: 07/28/2003

**DRAFT**

Note: If samples are not homogeneous, then subsamples of the components were analyzed separately. All bulk samples are analyzed using EPA 600/R-93/116 Method with the following measurement uncertainties for the reported % Asbestos (1%=0-3%, 5%=1-9%, 10%=5-15%, 20%=10-30%, 50%=40-60%). This report relates only to the items tested. If sample was not collected by NVL personnel, then the accuracy of the results is limited by the methodology and acuity of the sample collector. This report shall not be reproduced except in full, without written approval of NVL Laboratories, Inc. It shall not be used to claim product endorsement by NVLAP or any other agency of the US Government.

Page 2 of 2

RCLLC 0002085